



CSI Geo staff also provided geotechnical investigations and design services for the surrounding infrastructure including Bay Street (between Metro Park and the stadium) and other roadways, storm water drainage, and utilities. Geotechnical services included roadway pavement design recommendations for the various roadways and parking areas, and providing retention pond drainage data.

The work included:

- Reporting of existing site conditions
- Boring logs with a graphic representation of the soil borings
- Results of laboratory test performed
- A summary of all field and laboratory testing procedures performed
- Water table information
- A brief description of subsurface conditions encountered at each boring
- Evaluation of the subsurface conditions possible debris removal

Client

City of Jacksonville
Public Works Department

Sam Mousa

Location

Duval County, FL

Service(s)

- Geotechnical Engineering
- Construction Engineering Inspection
- Construction Materials Testing

Project Engineer(s)

- William Price
- Bruce Khosrozadeh, PE